

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 365 अनु

दलसिंहसराय/दिनांक 10/02/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान **Rs.-21.77625 (Twenty One Lakh Seventy Seven Thousand Six Hundred Twenty Five Rupess)** कि आवश्यकता है अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-21.77625 (Twenty One Lakh Seventy Seven Thousand Six Hundred Twenty Five Rupess)** उपलब्ध कराने कि कृपा कि जाये।

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फॉर्म।
3) IRI Report की छायाप्रति सलग्न।
4) मापिपुस्त की छायाप्रति सलग्न।

विश्वासभाजन


10.02.2021

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy-2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1		Gandhi Chowk NH-103 se Kishanpur Path Tak	10105088		2.30	58.13800	39.91800	20.28863		16.09.2020	29/01/2021	3529	25mm	5.10%	23.95080	23.95080	15.96615	Work Completed
2		Lagma se Baba Kewal Asthan Tak	10105079		1.90	37.25520	37.49400	18.71861		16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
3		NH- 28 Rupouli Panchyat Bhawan Se Mukhiya Shri Amarkant Choudhary Ke Char Tak	10105090	1835 / 24.06.2019	0.70	36.83030	29.76800	26.60049	68 MBD/2019-20 21.01.2020	16.09.2020	29/01/2021	3664	25mm	5.10%	23.81440	23.81440	5.81010	Work Completed
4		REO Path Bhojpur Chat Tak	10105085		2.40	71.27020	19.05000	10.08000		16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
					7.300	203.494	126.23000	75.68773							47.76520	47.76520	21.77625	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

Sr. Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto February 2021

New Maintenance Policy 2018(MR New)

PIU;- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	752.28171	752.28171	Certified that out of Rs-752.28171 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-750.53562 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-1.74609 Lakh remaining unutilized at the end of period under the time of completion
		752.28171	752.28171	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was


Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurements have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have observed


3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

File : C:\MYNew folder\New folder\22121824.Xls. Section No. : 83. Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$
 Name of Customer : Sona Infracon Pvt Ltd. Name of Work/ Road : NH- 28 Rupouli Panchayat Bhawan Se Mukhiya Shri



Handwritten signature and date:
 22/12/2020
 PS

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	Y = 0 * X ² + 1.136 * X + 132.5		
17/12/20	13:22:18	83	0.1	400	0	4000	4676	A	25.783347	85.7634	Curve	X = 4200		
17/12/20	13:23:0	83	0.1	350	10.1	3500	3200	A	25.783187	85.764325	Curve	Y = 4903		
17/12/20	13:23:29	83	0.1	350	10.1	3500	3400	A	25.78313	85.765353	Curve			
17/12/20	13:24:3	83	0.1	300	10.1	3000	3540	G	25.783112	85.76638	Normal			
17/12/20	13:24:38	83	0.1	230	10.1	2300	2745	G	25.783113	85.767357	Normal			
17/12/20	13:25:0	83	0.1	400	10.1	4000	3400	A	25.783152	85.76835	Normal	(R) RURAL ROAD		
17/12/20	13:25:14	83	0.1	400	0	4000	3800	A	25.783352	85.769325	Normal	Good	Average	Poor
17/12/20	13:26:0	83	0.1	400	10.1	4000	3600	A	25.78333	85.770337	Normal	<4000	4001-5000	>5001
17/12/20	13:26:24	83	0.1	440	10.1	4400	3400	P	25.783282	85.771347	Normal			
17/12/20	13:27:0	83	0.1	430	10.1	4300	3600	P	25.783193	85.772305	Normal			
17/12/20	13:27:35	83	0.1	520	0	5200	3800	P	25.783108	85.773315	Curve			
17/12/20	13:28:10	83	0.1	360	0	3600	4222	A	25.782492	85.773585	Speed Breaker			
17/12/20	13:30:0	83	0.1	550	0	5500	3800	P	25.781893	85.774023	Culvert			
17/12/20	13:42:17	83	0.1	620	0	6200	3600	P	25.782043	85.774073	Speed Breaker			
17/12/20	13:43:27	83	0.1	460	0	4600	3200	P	25.78256	85.773635	Normal			
17/12/20	13:44:38	83	0.1	300	0	3000	3540	G	25.783135	85.773282	Normal			
17/12/20	13:45:13	83	0.1	370	0	3700	4335	A	25.78318	85.772288	Curve			
17/12/20	13:46:0	83	0.1	350	0	3500	4108	A	25.783242	85.771312	Curve			

AP
17/12/20

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		2nd and 1st			641
Name of village → improvement of road					
From NH 28 to Rupoli Panchayat					
Bharwan se mulchhiya					
Sri Amar Kant choudhary					
ke Khatra Tale univ m R					
Heard					
Aam - Soda gntaroon Pvt. Ltd					
Audu - 68 MDD/2019-20					
Dedukt shat - 17.12.19					
Dedukt - 16.19.202					
Achari Guntaroon - 28.11.2020					
Dedukt shat - 29.1.2021					

① Name → Khat

[Signature]
29/11/2021


[Signature]
24/11/21
VKA

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Rs 2902535 =
19. Gt & plastering work					
all walls & ceilings					
Plaster for Gt work H 16					
at rate (19) 41.28 m ²					
@ Rs 156.19/m ²					Rs 6447 =
20. Gt & plastering work					
ceiling work done					
Plaster for Gt work H 16					
at rate (20) 41.28 m ²					
@ Rs 95.63/m ²					Rs 3948 =
					Rs 99,12,930 =

Add 1st. Gt & Pl. for ceiling	Rs 378681 =
	Rs 3291,611 =
less 1st. beam & slab	Rs 329161
	Rs 29,62,450 =
less 1st. floor	
less 1st. floor	Rs 23,81,440 =
	Rs 5,81,010 =


 29/11/21

 29/11/21
 AE

cap

 29/11/2021