## **Inspection Report for Flood Damage Work**

Date:-

1 Name of PIUs:- (gyan vibakard
2 Name of Block/Road:- Karter / To 1 - Bogami to Leukhampur greallopei)

(A) For Road:

:- 01600 lm 4 1,50 lm 1. Damage Location/Chainage

:- 0.080 Km 2. Damage Length

3. Nature of Damage

4. Details of Restoration Works:

Equipment's/Tools being used in Restoration works:- Force beat & Local sand

Procedure taken up in Restoration works:- Procedure taken up in Restoration works:-(i)

(ii)

(iii)

:- 000801cm Restored Length (iv)

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length :-

3. Nature of Damage

4. Details of Restoration Works:

Material being used in Restoration works:-(i)

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) कार्यपालक अभियंता य्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी71

## **GENERAL ABSTRACT**

Name of Road

T01-Bagani to Lakhanpur Road (ODR1)

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

2.124 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	4.40
3	Sand Filling	4.32
4	Sand bag	0.00
5	H.P.	0.00
	GRAND SUB TOTAL	8.73
TOTAL	COST OF PROJECT IN LACS =	8.73

RWD

Technically approved for AS 8-731 lac (Rupees Bight lac seventy three thousand one hundred only)

कार्व भंगत, मुजयफरपुर