

FIELD INSPECTION REPORT

Date of inspection: 31.5-1-2021	District: GAYA	
Division: Grooming & Balhant	Length (Km.): 0.755 km	
Scheme/Programme: MAINTENANCE		
Package No.: 2342229241 215 21	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance:	
Work is a case of:	New Connectivity/Up gradation/Maintenance:	
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road surface condition	S S/U
b)	Condition of Surface	S S/U
c)	Surface Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of RCC Pavement.	Yes Yes/No
f)	Contraction Joints provided or not (RCC Pavement)	Yes Yes/No
g)	Compaction of Bank/slope & rainouts if any	Yes Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SR/U
c)	Condition of railings/slab/approach for Bridges	NA S/SR/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/lan & 200m stones/Pavement road markings are provided and maintained.	Yes Yes/No
4	Compliance History	NO ATR
a)	Status of ATRs & any others.	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SM)	
Unsatisfactory (U)	

Chhetrapal
31.5-1-2021
J.B