

FIELD INSPECTION REPORT

Date of Inspection : 15.12.2019	District: Nandada
Division : Rajanli	Length (km): 0.600
Name of the Road: Hathachak to 1029	
Scheme/Programme: MAINTENANCE	on going.
Package No.: MM/LSY	Road Id No.: 105022013084
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	on going.
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NA

(Signature) Shubh
15/12/20

NAME: Sunil Kumar

DESIGNATION: AE