FIELD INSPECTION REPORT

		LIME			
Date of In	spection: 15	-0.2-2021		NAWADA	
Division :	RATI	A-11/-1	Length (km): 0 · 600		SANOKHARA
Name of	the Road: SA	MUDAIK BHAV	WAN BIGHAPARTO 34	TLALPUR	ROAD
Scheme/Programme: MAINTENANCE MMG27				, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Manager 1	No.: MA		Road Id No.: 1050270130	0034	
Status of the Project: Ongoing/Completed					
ALCOHOLDS VALVE	a case of:		Jp gradation/ Maintenance	Like Bridge Life	1
SII No.		Parameters to	be checked	Remarks	
j,	Pavement				
a)	Road Junction condition S/U				\mathbf{h}
b)	Condition of Surfacing			S/U	hork
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	Leodora in hosk
ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	1 1,000
,g)	Compaction of flank/slope & raincuts if any			Yes/No	
	Groat Drain				
a)	Condition of head walls in Hume pipe culverts including its painting S/S				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)		railings/slab/approach	S/SRI/U		
33	Road Furnit	11			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	Compliance	History			**
a)		R's & any others		NA	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NA

(Signature)

NAME: BINOD KUMAR
DESIGNATION: J.E., RWD.