

FIELD INSPECTION REPORT

Date of Inspection: 17-02-2021	District: NAWA DA
Division: RAJOLI	Length (km): 1.566
Name of the Road: KHATANGI PATH TO LAUNI	
Scheme/Programme: MAINTENANCE / IMPROV	
Package No.: NA	Road Id No.: 105027013013
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAU
b)	Condition of Surfacing	SAU
c)	Riding Quality	SAU
d)	Road Camber	SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
17-02-21

NAME: BINOD KUMAR

DESIGNATION: J.E, RWD