

FIELD INSPECTION REPORT

Date of Inspection	16.02.2021	District	NAWADA
Division	KA TALUKA	Length (km)	1.700
Name of the Road	WILHAR ROAD TO MAYAPRAKASH NAGAR		
Scheme/Programme	MAINTENANCE	MIVV 17	
Package No.	11A	Road Id No.	1050276130114
Status of the Project	Ongoing/Completed/Under Maintenance		
Work is a case of	New Connectivity/Up gradation/ Maintenance		


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & runcuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

work in progress

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NA

(Signature) 
16.02.21

NAME: BINOD KUMAR

DESIGNATION: J.C, RWD.