

FIELD INSPECTION REPORT

Date of Inspection : 15.12.2020	District: Navsari
Division : RAMUTLI	Length (km): 0.420 KM
Name of the Road: મામીપુર એ સિપરિયા રોડ	
Scheme/Programme:	MAINTENANCE
Package No.: -	Road Id No.: 10502701208
Status of the Project:	Ongoing/Completed/Under Maintenance mmhoy
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S J
b)	Condition of Surfacing	S J
c)	Riding Quality	S J
d)	Road Camber	S J
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings/slab/approach for Bridges	SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

NAME: SUSHIL

DESIGNATION: SR

15.12.2020
SR