## FIELD INSPECTION REPORT

Date of Inspection: 15.02.21			District: NAWADA		
Division: RADOLI			Length (km): 0.525kh		
Name of	the Road: 39		JP Nagar Paschim Trly		
Scheme/I	Programme:	MAINTENANC	CE GITSNY		
Package No.:			Road Id No.: 18502718006		
and the second second second second	the Project:		leted/Under Maintenance		
Work is	a case of:		ity/Up gradation/ Maintenance	THE REAL PROPERTY.	
Sl. No.		Parameter	rs to be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			_S/U	
b)	Condition of Surfacing			_S/U	
c)	Riding Quality			_S/U	
d)	Road Camber			_ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
0	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drain	age			
a)	Condition of head walls in Hume pipe culverts including its painting			Ş/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	VF
c)	Condition of railings/slab/approach for Bridges			S/SRI/U \	
3.	Road Furniture				
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	7
4.	Compliance History				1
a)	Status of AT	'R's & any others	S	The same	1

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: SUNTING

DESIGNATION: JE