FIELD INSPECTION REPORT

Date of Inspection: 25, 01, 21		District: Sand libre	
Division: 12 12 D. Ro Soon		Length (km):	
Name of the Road: 2	048-1037	KLaiza Rod	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		,
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Payement	一张连续·亚 第四位。在
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/Ų
c)	Riding Quality	S/V
d)	Road Camber	s/¥
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	s/sri/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)	ی	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

- NAME: Law Brasch fas who DESIGNATION: J/E (4)/her)

Scanned with CamScanner