## FIELD INSPECTION REPORT

Date of Inspection: 25.1.21		District: Samas Tipm		
Division: R ND. Rosuso'		Length (km):		
Name of the Road: MMG3Y- To2 to Dard No-1 Dala				
Scheme/Programme:	MAINTENANCE			
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	No. Parameters to be checked		
1.	Pavement	here is the	
a)	Road Junction condition	S/V	
b)	Condition of Surfacing	s/d	
c)	Riding Quality	S/ <b>V</b>	
d)	Road Camber	S/\psi	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No .	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ran Passed Passers
DESIGNATION: JE 141/10en

Scanned with CamScanner

(Signature)