

FIELD INSPECTION REPORT

Date of Inspection: 30-12-20		District: - Kishanganj
Division: - Kishanganj-I		Length(km): - 2.393 km
Name of the Road: LOTO - TOS TO Mandal TO19		
Scheme/Programme: PMGSY		
Package No.: BR-18R-71		Road Id No.: 21205802093
Status of the Project:		Ongoing/Completed /Under Maintenance
Work is a case of:		New Connectivity/ Up gradation / Maintenance
S1. No	Parameters to be checked	Remarks
1.	Pavement	✓S/U
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank / shop & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	-S-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Radheshyam prajapati
J.E, Bahadurganj-I


 30.12.20
 J.E
 (Signature)