FIELD INSPECTION REPORT

Date of	Inspection: 30.	12.020	Dis	strict: Kishanganj		
Division: Kishanganj-1			Lei	Length(km): 2-806 Kan.		
Name o	of the Road: PM	asy road t	palbo	edi to mahammed meser.	via Herei	
	e/Programme:	mmasy (200	that were	
Packag	e No.:			Road Id No.: 21205812010		
Status	of the Project:	Ongoing/Com	plete	d /Under Maintenance		
Work is	a case of:	The Control of the Co	And the second second	Up gradation / Maintenance		
\$1. No			PRODUCTION OF THE PARTY OF THE	be checked	Remarks	
1.	Pavement		ST 22		S/U	
a)	Road Junction Condition				~\$/U	
b)	Condition of Surfacing				'S/U	
c)	Riding Quality				'S/U	
d)	Road Camber				'S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No		
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank / shop & raincuts if any			Yes/No		
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U		
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U		
3.	Road Furniture					
a)	Whether sign b	ooards/informa	tory/c	autionary Board/km & 200m	Yes/No	
	stones/Paveme	ent road markir	ngs are	provided and maintained		
4.	Compliance Hi	story				
a)	Status of ATR's	& any others				

Overall Rating:

Satisfactory(S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory(U)		

NAME: RAKESH KUMAR.