FIELD INSPECTION REPORT

The second secon	f Inspection: 30.	12.020	District: Kishanganj		
Division: Kishanganj-1			Length(km): 2-609 Km		
Name o	of the Road: Pr	rasy Rock	to makeut tola		
Scheme	e/Programme:	mmasy ca			
Package	e No.:		Road Id No.: 21205812025.		
Status of the Project: Ongoing/Comp		Ongoing/Compl	leted /Under Maintenance		
Work is	a case of:		ity/ Up gradation / Maintenance		
S1. No			s to be checked	Remarks	
1.	Pavement			'S/U	
a)	Road Junction Condition			S/U	
b)	Condition of Surfacing			~S/U	
c)	Riding Quality			~\$/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank / shop & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign be	oards/informator	ry/cautionary Board/km & 200m	Yes/No	
	stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's	& any others			

Overall Rating:

Satisfactory(S)			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory(U) \			

(Signature) \$\frac{1}{30.12.020}\$

NAME: RAKESH KUMAR.