


FIELD INSPECTION REPORT

Date of Inspection:- 30.12.20		District:- Kishanganj	
Division:- Kishanganj-I		Length(km): 3.972 KM	
Name of the Road: Patlu Chowk L.R.P TO Bhalani School Deharomalmi via Kabir Chowk			
Scheme/Programme: Madan Tolga		MMGS-4	
Package No.: N.A		Road Id No.: 21205814001	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank / slope & rain cuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	-U-


 J.E 30.12.20
 (Signature)

NAME: Radheshyam prajapati
 J.E, R.W.D. Bahadurganj-I