FIELD INSPECTION REPORT

_	4	TO REPORT	
Dat	e of Inspection: 23.12.2000	District: Town and	
	ision: Trailing	201181000	2000
Nan	ie of the Road: Sich !: bat	7 130	215
Sche	me/Programme: MAINTINA	La Company	want 1
Pack	age No.: PR-150 DIE	h14(0/24	
Statt	is of the Project: Ongoing/Con	npleted/Under Maintenance	2.01
Worl	k is a case of: Vew Connect	ivity/Up gradation/ Maintenance	
SI. N	o. Paramet	ers to be checked	D.A. ADAM
c 1.,			Remarks
a)	Road Junction condition		
b)	Condition of Surfacing		870
c)		√S/U	
d)	Riding Quality		√ 8/Û
<u>u)</u>	Road Camber	V8/U	
c)	Whether free from defects aggregates in case of CC Paver	Yes/No	
f)	Contraction Joints provided or	Yes/No	
g)	Compaction of flank/slope & raincuts if any		Ves/No
2.	Cross Drainage		
a).	Condition of head walls in Hume pipe culverts including its painting		► S/8RI/U
b) *	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approa	ach for Bridges	S/SRI/U
3.	Road Furniture		
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
	Compliance History		
15	Status of ATR's & any others		en telle e sa

Overall Rating

Satisfactory (S)	0
Satisfactory but requires Improvement (SRI)	>
Unsatisfactory (U)	

NAME: Proposh by Mahr

DESIGNATION:

(Signature) 23.12.70 TO