FIELD INSPECTION REPORT

| - | espection: 06-12-1070 D | District: Damul | |
|---|--|------------------------|--------------|
| | ispection 1 | ength (km): 0-945 | |
| ivision : | 1/00/1/09 | POD Rd to GO | neigra |
| Name of | MAINTENANCE | PMOISY | • |
| Package No.: BR 15R369 Road Id No.: 2080420 S | | | 2204 |
| | The Project: Ongoing/Completed/Un | nder Maintenance | |
| | a case of: New Connectivity/Up s | gradation/ Maintenance | |
| Sl. No. Parameters to be checked | | | Remarks |
| 1.,, | Pavement | | |
| a) | Road Junction condition | | : 87U |
| b) | Condition of Surfacing | | S/U |
| c) | Riding Quality | | ⊸ S/U |
| d) | Road Camber | | _S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | .Ves/No |
| f) | Contraction Joints provided or not (CC Pavement) | | Yes/No. |
| g) | Compaction of flank/slope & raincuts if any | | Yes/No |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | S/SRI/U |
| b), | Condition of Abutment & Wing walls, Slab in RCC culverts | | S/SRI/U NA |
| c) | Condition of railings/slab/approach for | Bridges | S/SRI/U |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | Yes/No |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | 1,7 |

Overall Rating

| Satisfactory (S) | Q |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Probable ky Mahlo DESIGNATION: JE