

FIELD INSPECTION REPORT

Date of Inspection : 19-12-2020		District: Jalore
Division : Jhalga		Length (km): 1.198 km
Name of the Road: L143 PM6154 Kusauna Rd to Thakernwanti		
Scheme/Programme: MAINTENANCE		PM6154
Package No.: BR-15R 370		Road Id No.: 20804202205
Status of the Project: Ongoing/Completed/Under Maintenance		<input checked="" type="checkbox"/>
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<input checked="" type="checkbox"/> S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Prakash kumar
19.12.2020

DESIGNATION: SE

Prakash
(Signature) 19.12.2020