

FIELD INSPECTION REPORT

Date of Inspection : 20.12.2020		District: Jamnol
Division : Jhalga		Length (km): 1.09 km
Name of the Road: PMGSY Khairan Rd to Bongyara		
Scheme/Programme: MAINTENANCE		PMGSY
Package No.: BR-15R 368		Road Id No.: 20804202207
Status of the Project:		Ongoing/Completed/Under Maintenance ✓
Work is a case of:		✓ New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

NAME:

Prabakar kumar
20.12.2020

DESIGNATION:

SE

(Signature)

Prabakar
20.12.2020