## FIELD INSPECTION REPORT

Date of	Inspection: - 3	10:12:20	Distri	ct: - Kishanganj	
Division: Kishanganij-1		Length(km): - 4-75 KiM			
			2 or a re	Jurgapur Bangama	
	/Programme:	PMGSY		0	
Package	No.:			oad Id No.: 21205802129	
Status of the Project: Or		Ongoing/Cor	oing/Completed /Under Maintenance		
Work is a	a case of:	New Connec	ctivity/ Up	gradation / Maintenance	
\$1. No		Paramet	ters to be	checked	Remarks
1.	Pavement				
a)	Road Junction Condition			~57U	
b)	Condition of Surfacing			√5/U	
c)	Riding Quality				VS/U
d)	Road Camber			V5/TU	
e)	Whether free	from defects s	uch as visi	ble cracks, exposed aggregates	Yes/No
	in case of CC Pavement.				
f)	Contraction Joints Provided or not ( CC Pavement)			Mes/No	
g)	Compaction of flank / slope & rain cuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			~5/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			√S/SRI/U	
3.	Road Furniture				
a)	Whether sign	Yes/No			
	stones/Paver	ment road mark	kings are p	rovided and maintained	
4.	Compliance I				
a)	Status of ATR's & any others			NO	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

(Signature)

NAME: Radheshyam porajapati J.E., Bakadusgang. I