


FIELD INSPECTION REPORT

Date of Inspection: 30.12.020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 2.00 km.	
Name of the Road: PMGSY Road to Dekhshin Belti Dulali			
Scheme/Programme: GTSNY.			
Package No.:		Road Id No.: 21205818018	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
Sl. No	Parameters to be checked	Remarks	
1.	Pavement	✓S/U	
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank / shop & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory(U)	


 30.12.020
 (Signature)

NAME: RAKESH KUMAR.