


## FIELD INSPECTION REPORT

Date of Inspection: 30.12.20		District: Kishanganj	
Division: Kishanganj-5		Length(km): 1.20 K.M	
Name of the Road: Dewari to Sahadi			
Scheme/Programme: GTSNY			
Package No.: N.A		Road Id No.: 21205801846	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
Sl. No	<u>Parameters to be checked</u>		Remarks
1.	<b>Pavement</b>		
a)	Road Junction Condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Contraction Joints Provided or not ( CC Pavement)		✓Yes/No
g)	Compaction of flank / slope & rain cuts if any		Yes/No ✓
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		- N.A S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		- N.A S/SRI/U
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		Yes

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	-U-

  
 30.12.20  
 J.E.  
 (Signature)

NAME: Radheshyam prajapati  
 J.E, Bahadurganj-5