


FIELD INSPECTION REPORT

Date of Inspection: 30.12.20		District: - Kishanganj	
Division: Kishanganj-I		Length(km): 1.40 KM	
Name of the Road: Dewari Tola to Laxmi Tola			
Scheme/Programme: GTENY			
Package No.: N/A		Road Id No.: 21205801847	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		
a)	Road Junction Condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank / slope & rain cuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		N/A S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		N/A S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	- SRI -
Unsatisfactory (U)	-


 30.12.20
 J.E.
 (Signature)

NAME: Radheshyam prajapati
 J.E., Bahadurganj - 1