FIELD INSPECTION REPORT

Date of Inspection: MA			District: Carrier and					
Division: Lakhisarai			Lukusgoa					
Name of the Road: To12 ODR to ofapur Mysher=								
Scheme/Programme: MAINTENANCE NA								
Package No.: Road Id No.:								
Status of the Project:		Ongoing/Completed/Under Maintenance						
Work is a case of:		New Connectivity/Up gradation/ Maintenance						
Sl. No.		Parameters to	be checked	Remarks				
-1.	Pavement			and out on				
a)	Road Junction condition S/U							
b)	Condition of S	S/U						
c)	Riding Quality	S/U						
d)	Road Camber	S/U						
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No							
f)	Contraction Jo	Yes/No						
g)	Compaction of	Yes/No						
2	Cross Drainage							
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U							
b) .	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U							
c)	Condition of ra	S/SRI/U						
3.	Rond Furniture							
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No							
4.	Compliance I	listory						
a)	Status of ATR's & any others							

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

31-12-2020

MA

(Signature)

N	A	M	E
		.,,	