



Inspection Report For Flood Damage Work

FY	23		1	ú
U	а	τ	e	9

Gobalgary - 2 1 Name of PIUs:

2 Name of Block/Road: Bai Kuntipus / mararari Panolohi PMGSY Palls 90 For Road manswrigg Pancheyas Sadala

1 Damage Location / Chainage:

200m to 750m

2 Damage Length:

286 m

3 Nature of Damage:

Heavy Rain / Flood

4 Details of Restroration Works:

i. Material being used in Restoration Works:

Botck Bats

ii Equipments / Tools being used in Restoration Works: TeB, Truloz, showed, seles, Troli

iii Procedure taken up in Restoration Works:

iv Restored Length:

286 m

B For Bridge

NIA

1 Damage Location / Chainage:

2 Damage Length:

3 Nature of Damage:

4 Details of Restroration Works:

i. Material being used in Restoration Works:

ii Equipments / Tools being used in Restoration Works:

iii Procedure taken up in Restoration Works:

iv Restored Length:

Report

Name of Work

:- Motorable work of Maharani Pandohi PMGSY Path To Mansuriya Panchayat Sadak

Estimated Cost

:- .20351000.00 20,35,800 200

Ps 1865000 =00

Total length of Road

:- 1.505 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road. Hence there has been a provision of laying 1 Nos of R.C.C. NP3 1000 MM Dia hume pipe.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

191912020 191912020 J.E.

A.E.

EF 1919/20

Detailed Estimate For Motorable Work in Road from Maharani Pandohi PMGSY Path To Mansuriya Panchayat Sadak damaged due to Heavy rain/flood for year 20202021

				2021		TC 5000	Theodor igns		Various occurs surrens
Sr.	Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
1	Providing brick bats billed in ditches including all cost of labour & material with all complete job.		19.100	1.20		71.2-0			
	CH - 200 M to 750 M	1	12.00 -14.00	-1.50	0.50	-10.50	M3		
		1	5140	-1.20	0.40	2 v 1 5 -2.88	M3		
		1	8.00	3.00	0.90	21.60	M3		
	110	1	20.00	3.50	2.00	140.00	M3		0/
		1	25.00	1.20	2.00	60.00	M3		
		1	21.00	1.80	1.40	52.92	M3		
		1	4.00	2.50	1.50	15.00	M3		
		1	30.00	3.75	0.85	95.63	М3		
		1	15.00	1.20	0.35	6.30	МЗ		
		1	-29.00	4,50 -5:00	1.20	174.00	МЗ		
-		1	-26+00 -30.00	- 3.00	0.60	-54.00	М3		
=		1	14.00	3.50	1.40	68.60	МЗ		
		1	11.00	2.00	0.40	8.80	МЗ		
		1	9.00	2.60	0.60	14.04	МЗ		
		1	8.00	2.80	0.85	19.04	МЗ		
		1	7.00	3.00	1.00	21.00	M3		
		1	16.00	1.65	1.25	33.00	МЗ		
		1	19.00	0.80	2.00	30.40	МЗ		
	Less for H.P.	0.79	1.23	1.23	5.00	5.98	M3	2412-11	1814076=
						821.73		2427:65	1994870,52
2	Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	2	2.50			752.04 5.00	м	2744-50 - 4159.56 -	1846 5812
								18277993	78 4653813
	Add 1 % Contigency							18278=-	18465158 -20156.68 1865023-2
						184607	. J. V	Total	- 2035825.0 0
						Bery M.	18.461	Usay	20351000.00

Te chrically Approval for Re 20. 36 to Repose


1919/20 3620

Ps 1865000 200

PDF Compressor Free Version

			(d)	A Int	WU .		Berliet in a frame and	
							2011 A 001 H3	
							ghteen lev	
		- et		- 1	10. Ar	es Gi	ghteen lee	
- 1	75	1 for	R 18.	461 600	Check		V	
Inica	lly App	reveal di	me It	undv-c) cru	7		
inty Pi	u/ Thou	served ip	15.					
S. A.	10	DE AND		301 2	£,25			
	1 804 (mily	÷ m	188	HURS			
	165	(क्षण अस्तर	er Versan	12 5	10 th	1		
	ग्रामाण का	व विभाग अस	2	15.2	100	1		
	1.10	O los MAIN	X	25 L	17 -1			
	15.0	12 15 m-1		THIS		7		(**)
	24	100-21	E 0	75 FT - 7"	100 B	Y.		
	1 8 14	(3.45)	Sect.		35.45			j.
	10.00	0.22	Ture T		00 11	2		
	I EM	1 44.5	200	na.s	155-15			
	E 122		12.1	(415)	10- g		15	
_			310.4	88.5	£1.7.7.			
			12.1	76.3	90 (8)	1		
			1 605	45.8	1 187.42			
		2 162	2E-2	10.0	13.3	85-37	3.36 (arteres)	
Lanta-	ce.534	75 168						
							Mechany which somewhal	
estuants.	SHOWE	18 X 2	1		92.5	1 4 1	deplet in and hange is a city	5
Mar Cycl			4		-		trous on development	
SEAL ELYL		interior and the second		-		-		
Edit 24			4		-		A Algebra Control of	100
	\$410 A 1	1.34	i -		- Indonesia in			يهاود
10113 (6.0)	1 4		And in	.1	1	1	1	
								-
at 1 5							The Hard Street	8
	3.2	2.000		9-74	e 1 4	, ye		
	New York	14 7				W.T		
Out they	19	A. 124		1 WOS. 1 2				
		F 1 100		2				4
ide.				May be	37	N 3		185
	and the second second							
光	San 3 / 10	in the second second	A CONTRACT	Sent E		71 CON 1 CON 1 W		-

Name of Road :- Maharani Pandohi PMGSY Path to Mansuriya Panchyat Sadak





Name of Road :- Maharani Pandohi PMGSY Path to Mansuriya Panchyat Sadak

