

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District : Purnea	
Division : Purnea		Length (Km) : 1.117	
Name of the Road : Dharan Mandal Road to adiwari to 9			
Scheme/Programme :		Maintenance	
Package No. :		Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of :		New Connectivity/Up gradation/Maintenance <input checked="" type="checkbox"/>	
Sl. No	Parameters to be Checked	Remarks	
1). Pavement			
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U	
b)	Condition of Surfacing	S/U <input checked="" type="checkbox"/>	
c)	Riding Quality	S/U <input checked="" type="checkbox"/>	
d)	Road Camber	<input checked="" type="checkbox"/> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No	
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No <input checked="" type="checkbox"/>	
2). Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U <input checked="" type="checkbox"/>	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U	
3). Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No <input checked="" type="checkbox"/>	
4). Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	
Status :	

Name : Rajendra Kumar
 Designation : S.E.
 RWD, Works Division, Purnea.

20/12/2020
 19.12.2020
 (Signature)