

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020		District : Purnea	
Division : Purnea		Length (Km) : 1.146	
Name of the Road : Middle School to Sak tolg			
Scheme/Programme :		Maintenance	
Package No. :		Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance ✓	
Work is a case of :		New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked		Remarks
1). Pavement			
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		S/U ✓
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No ✓
2). Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U N/A
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U N/A
3). Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		Yes/No ✓
4). Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	
Status :	

Name : Ramkalyan Kumar
 Designation : J-C
 RWD, Works Division, Purnea.

21/01/2021
 17-12-2020
 (Signature)