

FIELD INSPECTION REPORT

Date of Inspection : 22-12-2020		District : Purnea
Division : Purnea		Length (Km) : 1.707
Name of the Road : Tappu Tola to Adwasi Tola		
Scheme/Programme :	Maintenance	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance ✓	
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	SU ✓
c)	Riding Quality	SU ✓
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes No
g)	Compaction of Flank/Slope & Raincuts if any	Yes No ✓
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	SSRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	SSRIU
c)	Condition of Railings/Slab/Approach for Bridges	SSRIU
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes No ✓
4).	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	
	Status :	

Name : Ranu day Kumar
 Designation : J.E
 RWD, Works Division, Purnea.

22-12-2020
 (Signature)