


## FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District : Purnea
Division : Purnea		Length (Km) : 1.573
Name of the Road : Basid ke Ghar to adiwasi to/a		
Scheme/Programme :	Maintenance ✓	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance ✓	
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked	Remarks
<b>1).</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U ..
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No ✓
<b>2).</b>	<b>Cross Drainage</b>	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U ✓
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U ✓
<b>3).</b>	<b>Road Furniture</b>	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
<b>4).</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	U
	Status :	

Name : Ram uday Kumar  
 Designation : J.C  
 RWD, Works Division, Purnea.

  
 18.12.2020  
 (Signature)