

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District : Purnea	
Division : Purnea		Length (Km) : 1.050 Km	
Name of the Road : Phasia chook to Borkan Sma			
Scheme/Programme :		Maintenance	
Package No. :		Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked		Remarks
1).	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		S/U ✓
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No ✓
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No ✓
2).	Cross Drainage		
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U ✓
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U ✓
3).	Road Furniture		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		Yes/No ✓
4).	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	
Status :	

Name : Ramuday Kumar

Designation :

RWD, Works Division, Purnea.

20/12/20
18.12.2020
(Signature)