

BHOREY

Date of Inspection :	28.12.2020	District:	GOPALGANJ
Division:	HATHUA	Length (km):	1.287
Name of the Road:	BINREY-BANARA DMSSY ROAD TO BHIRUA CHAPAR		
Scheme/Programme:	MAINTENANCE	MTMGSSY CSC)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	☒ S/U	
b)	Condition of Surfacing	☒ S/U	
c)	Riding Quality	☒ S/U	
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

Raincut in RCC Pavement should be repaired.

(Signature)
28/12/2020

NAME: Arun Kumar Singh

DESIGNATION: JE