FIELD INSPECTION REPORT

Date of Inspection: 15-12-2020		District: or log marke	
Division: Gitamarhi		Length (km): 1.45 /45	
Name of the Road: R		o roadhyhan	
Scheme/Programme:			
Package No.: AR-83+R 397		Road Id No.:	
the state of the s	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	150
a)	Road Junction condition	_S/U
b)	Condition of Surfacing	_8/U
c)	Riding Quality	S/U
d)	oad Camber	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	4
a)	Condition of head walls in Hume pipe culverts including its painting	_S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_S/ŚRI/U
c)	Condition of railings/slab/approach for Bridges	_8/SRI/U
3.	Road Furniture	· Y- Y
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5RT.
Unsatisfactory (U)	

(Signature)

NAME: DESIGNATION: Junior Engl.