


Location: 2412-241 District: Cash Chakporag  
 Name of the Road: By-pass Length (km): 2.5 km  
 Scheme/Programme: Pavement to Kumbha Mela  
 Package No.: MAHATTA  
 Status of the Project: Completed Road ID No.: 213 4312009  
 Work is a case of: Regular Maintenance

| Parameters to be checked |                                                                                                                      | Remarks  |
|--------------------------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.                       | <b>Pavement</b>                                                                                                      |          |
| a)                       | Road Junction condition                                                                                              |          |
| b)                       | Condition of Surfacing                                                                                               | ✓        |
| c)                       | Finishing Quality                                                                                                    | ✓        |
| d)                       | Road Camber                                                                                                          | ✓        |
| e)                       | Whether free from defects such as surface cracks, exposed aggregates in case of CC Pavement.                         | ✓        |
| f)                       | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No ✓ |
| g)                       | Compaction of flank/slope & raincuts (if any)                                                                        | Yes/No ✓ |
| 2.                       | <b>Cross Drainage</b>                                                                                                |          |
| a)                       | Condition of head walls in Hume pipe culverts including its paving                                                   | ✓/SRI/U  |
| b)                       | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓/SRI/U  |
| c)                       | Condition of railings/slab/approach for Bridges                                                                      | ✓/SRI/U  |
| 3.                       | <b>Road Furniture</b>                                                                                                |          |
| a)                       | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓/No ✓   |
| 4.                       | <b>Compliance History</b>                                                                                            |          |
| a)                       | Status of ATR's & any others                                                                                         | No       |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | 3 |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | 0 |

  
 (Signature)