


FIELD INSPECTION REPORT

Date of Inspection:	31.12.20	District:	East Champaran
Division:	Barahat	Length (km):	2.9 km
Name of the Road:	Dumukhri Phamuki to 8A to Milkana full via Lach full		
Scheme/Programme:	MAINTENANCE	Road Id No:	317083/2010
Package No:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New/Improvement/Regular Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Good location condition	SI ✓
b)	Condition of Surfacing	SI ✓
c)	Finishing Quality	SI ✓
d)	Road Camber	SI ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Construction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of back/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI ✓
c)	Condition of railings/slab approach for Bridges	S/SRI ✓
3.	Road Furniture	
a)	Whether sign boards/informative/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	4


(Signature)

Munshi Kumar



Shot on Y12

Vivo AI Camera