

# FIELD INSPECTION REPORT

Date of Inspection:	21-12-20	District:	East Champaran
Division:	Bhagalpur	Length (km):	1.40 km
Name of the Road:	Lokariga Naha Khatola to Singhfolly		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road ID No.:	21700312013
Status of the Project:	Existing/Completed/Under Construction		
Work is a case of:	New/Improvement/Regular Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓	
b)	Condition of Surfacing	S/S ✓	
c)	Rating Quality	✓	
d)	Road Camber	S/S ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincut if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/NI ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/NI ✓	
c)	Condition of railings/slab/approach for Bridges	S/S/NI ✓	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

*[Signature]*  
21/12/20  
(Signature)

NAME: Manish Kumar  
DESIGNATION: J. E. P. W. Officer



Shot on Y12  
Vivo AI camera