

FIELD INSPECTION REPORT

Date of Inspection:	31-12-20	District:	East Champaran
Division:	Bharni	Length (km):	1.05 km - 1.26 km
Name of the Road:	Pakeriya Mouja Badhari shah house to Ram		1.05 km
Scheme/Programme:	MAINTENANCE		1.05 km
Package No.:		Road Id No.:	3170031205
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓/U	
b)	Condition of Surfacing	✓/U	
c)	Riding Quality	✓/U	
d)	Road Camber	✓/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting.	S/SRI ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Signature
31/12/20



NAME: Manish Kumar
Shot on Y12
Vivo AI camera
DESIGNATION: P.W.D. Officer