

ROAD INSPECTION REPORT

Date of Inspection: 20/10/2020 Name: [Signature]
 Location: [Signature] Length: 1.451 km
 Project No.: [Signature] Road No.: 705093/7004
 Name of the Project: [Signature]
 Name of the Inspector: [Signature]

Remarks: [Signature]

1. Pavement

2. Road Surface Condition

3. Condition of Surfacing

4. Riding Quality

5. Road Width

6. Weather: [Signature]

7. Construction: [Signature]

8. Condition of Road: [Signature]

9. Drainage

10. Condition of Road: [Signature]

11. Condition of Road: [Signature]

12. Condition of Road: [Signature]

13. Road Furniture

14. Weather signs: [Signature]

15. Condition of Road: [Signature]

16. Condition of Road: [Signature]

17. Condition of Road: [Signature]

18. Condition of Road: [Signature]

19. Condition of Road: [Signature]

20. Condition of Road: [Signature]

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SR)

Unsatisfactory (U)



Shot on Y12
Vivo AI camera