

MMGSY-SC
FIELD INSPECTION REPORT

Date of Inspection : 25/12/2020		District: Samantpur	
Division : Samantpur		Length (km): 0.725 km	
Name of the Road: Mohindipur - Digambar matka 1036 ke ghur Se			
Scheme/Programme: MAINTENANCE		Mahadukt Tola Tale	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		SAU
b)	Condition of Surfacing		SAU
c)	Riding Quality		SAU
d)	Road Camber		SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)		Yes/No ✓
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SB/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		— No —

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
(Signature)

NAME: RESHI RAJ