

# FIELD INSPECTION REPORT

Date of Inspection :	31-12-20	Location :	East Chumburay
Division :	Barraj	Length (km) :	0.60 km
Name of the Road :	Losa to Parha Rd		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	31700319015
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New/Continuity/By gradient Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Yes ✓
b)	Condition of Surfacing	Yes ✓
c)	Finishing Quality	Yes ✓
d)	Road Camber	Yes ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes ✓
f)	Construction Joints provided or not (CC Pavement)	Yes ✓
g)	Compaction of Back/slope & pavements if any	Yes ✓
2.	Cross Drainage	
a)	Condition of head walls in House type culverts including its painting.	Yes ✓
b)	Condition of Abutment & Wing walls, Slope in MCC culverts	Yes ✓
c)	Condition of railings/slope approach for Bridges	Yes ✓
3.	Road Furniture	
a)	Whether sign boards/informative/customary Board km & Dist. stones/Pavement road markings are provided and maintained	Yes ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

*[Signature]*  
31/12/20  
(Signature)

NAME: Manish Kumar  
DESIGNATION: J.E.R.-W.D. Barraj



Shot on Y12  
Vivo AI camera