

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2022		District : Purnea
Division : Purnea		Length (Km) : 0.305
Name of the Road : Sanjay Yadav Pargana to Unesh podder		
Scheme/Programme :		Maintenance
Package No. :		Road ID No. :
Status of the Project :		Ongoing/Completed/Under Maintenance ☒
Work is a case of :		New Connectivity/Up gradation/Maintenance ☒
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any	☒ Yes/No
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U ☒ A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U ☒ A
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U ☒ A
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	☒ Yes/No
4).	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	
	Status :	

Name : Ranu Yadav Kumar
 Designation : J.C.
 RWD, Works Division, Purnea.

22.12.2022
 (Signature)