

FIELD INSPECTION REPORT

Date of Inspection: 21-12-20 District: Deotchaibany
 Division: Baramy Length: 29.66 Km
 Name of the Road: Deotchaibany Baidig - 100m to Chhannaga Baidig 100m
 Scheme/Programme: (SELECT STATE) Road Id No.:
 Status of the Project: (Improvement/Completed/Under Construction)
 Work is a case of: (New/Rehabilitation/Upgradation/Maintenance)

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road function condition	✓
b)	Condition of Surfacing	✓
c)	Finishing Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of Gt. Pavement	Yes/No ✓
f)	Contraction Joints provided or not (Gt. Pavement)	✓/No
g)	Compaction of flank/slope & raincuts if any	✓/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	✓ SRI
c)	Condition of railings/slab/approach for Bridges	✓ SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/lan & 200m stones Pavement road markings are provided and maintained	✓ No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

S


 (Signature)

NAME: Manish Kumar

SIGNATURE: J-E-R-W-D. Arany



Shot on Y12
 Vivo AI camera