

FIELD INSPECTION REPORT

Date of Inspection:	31.12.20	District:	East Champaran
Division:	Boera	Length (km):	2.60 km
Name of the Road:	Singha Burka to Dhainsara		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.: 31705301320		
Status of the Project:	Ongoing <input checked="" type="checkbox"/> Completed <input checked="" type="checkbox"/> Maintenance <input checked="" type="checkbox"/>		
Work is a case of:	New Connectivity <input checked="" type="checkbox"/> Up gradation <input checked="" type="checkbox"/> Maintenance <input checked="" type="checkbox"/>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓ No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting.	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: Manish Kumar

DESIGNATION: J-E R-W-D-Boera