


FIELD INSPECTION REPORT

Date of Inspection:	31-12-20	District:	East Champaran
Division:	Arerua	Length (km):	0.750 km
Name of the Road:	Ullas Mahto	to	Kubra Mulla
Scheme/Programme:	MAINTENANCE	Road Id No.:	31708301823
Package No.:			
Status of the Project:	Ongoing/Completed/Up gradation/ Maintenance		
Work is a case of:	New Connectivity		

SL No.	Parameters to be checked	Remarks
1.	Pavement	✓
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	Yes/No ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	✓ SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	Yes/No ✓
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	No
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	SR1
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	


 31/12/20
 (Signature)

NAME: Munish Kumar