

FIELD INSPECTION REPORT

Date of Inspection:	21.11.20	District:	East Champaran
Division:	Buxar	Length (km):	0.60 km
Name of the Road:	Berha Berha to Perha to Perha tola-2		
Schema/Programme:	MAINTENANCE		
Package No.:	Head Id No: 317 0830 1828		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New/Rehabilitation/Up gradation/ Maintenance		
Sd. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)		Yes/No ✓
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/S/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/S/U ✓
c)	Condition of railings/slab/approach for Bridges		S/S/U ✓
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

(Signature)

NAME:

Manish Kumar

DESIGNATION:

J. E. R. W. O. Arerij



Shot on Y12
Vivo AI camera