


# FIELD INSPECTION REPORT

Date of Inspection:	31-12-20	District:	East Champaran
Division:	Barh	Length (km):	2.60 km
Name of the Road:	Kuma to Sahariga		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New/Continuity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SV
b)	Condition of Surfacing	SV
c)	Fading Quality	SV
d)	Road Camber	SV
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its pointing	SV
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SV
c)	Condition of railings/slab approach for Bridges	SV
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

  
(Signature)

NAME: Manish Kumar



Shot on Y12