

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District : Purnea
Division : Purnea		Length (Km) : 1.575
Name of the Road : Ramoo Tola to L228 (Saraswati Tola)		
Scheme/Programme :	Maintenance	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any	✓ Yes/No
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	✓ Yes/No
4).	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Status :	

Name : Ram uday Kumar

Designation : J.C.

RWD, Works Division, Purnea.


 19.12.2020
 (Signature)