

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District : Purnea	
Division : Purnea		Length (Km) : 1.638 Km	
Name of the Road : Bologna to Fasia South side			
Scheme/Programme :		Maintenance	
Package No. :		Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance ✓	
Work is a case of :		New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked		Remarks
1).	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any		✓ Yes/No
2).	Cross Drainage		
a)	Condition of Head walls in Hume Pipe Culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U
3).	Road Furniture		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		✓ Yes/No
4).	Compliance History		
a)	Status of ATR's & any others		


Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Status :	

Name : Ranuday Kumar

Designation : S-G

RWD, Works Division, Purnea.


 19.12.2020
 (Signature)