

FIELD INSPECTION REPORT


Date of Inspection : 22/12/2020	District: Bhospur
Division : A20	Length (km): 2.425
Name of the Road: A20 Bhatnagar Road to Dhundhwa	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 10401601901
Status of the Project:	☒ Ongoing/Completed Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & cutouts if any	Yes/No N.A.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No N.A.
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I.
Unsatisfactory (U)	

primix carpet not done.


(Signature)

NAME: