FIELD INSPECTION REPORT

Date of I	nspection : 3	1/2/2020	District: Juni		
Division		The state of the s	Length (km): 0.278		
	the Road: Lo	99- TO2 DORAP	to Sogra,		
	Programme:	MAINTENANC	E		
Package No.:			Road Id No.: 20804100	Road Id No.: 20804100216	
	the Project:		eted/Under Maintenance		
Oscillar and American	a case of:	New Connectivit	y/Up gradation/ Maintenance	ATT - Land of the	1
Sl. No.		Phrameters	to be checked	Remarks	
1.	Pavement			10 / 12 / 87 / 18 /	a
a)	Road Junction condition			S/U 9	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	ongoir
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drain:	gi i			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniti	ite			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance	是在1964年 2014年2月			
a)	Status of ATR's & any others			Yes	
Overell	Dating .			N.A	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NAME:

DESIGNATION:

Fuj 31/12/2020 (Signature)