FIELD INSPECTION REPORT

Date of Inspection: 10 12, 2020			District : Purnea	
Division : Purnea			Length (Km): 0.550	
lame of t	he Road: Ro	176971 Marour + F	oftwo gons.	
Scheme/Programme : Maintenance				
Package No. :			Road ID No.:	
Status of the Project: Ongoing/Completed/Under Ma			enance	
Work is a case of: New Connectivity/Up gradation/Maintenance			Maintenance	
Sl. No Parameters to be Checked			Remarks	
1).	Pavement	Carlos Tarrida		671
a)	Road Junction	on condition		VS/U
b)	Condition of Surfacing			√S/U
	Riding Quality			√S/U
c)	Road Camber			✓S/U
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of			Ves/No
	CC Pavement. Contraction Joints provided or not (CC Pavement)		√Yes/No	
f)	Compaction of Flank/Slope & Raincuts if any		Yes/Nov	
g)	Cross Drainage			
2).	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U
b)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U	
c)				
a).	Road Furniture Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No
4).	Compliance History			Control State
a)	Status of ATR's & any others			
0	Rating :	Satisfactory (S)		
Overall F	varing .	Satisfactory but requires Impro	vement (SRI)	SRI

Name: Ramaday Kumor

Unsatisfactory (U)

Status :

Degisnation: J-G

RWD, Works Division, Purnea.

(Signature)